



FIG. 1



F. 2

300 ↙



F.3




Fig. 4






Fig 5.

Vacuum adapter for sewing inside the chamber






Fig 8




FIG. 9